

Møte – Sikkerhetsforum 16.02.2017 Sam Samuelsen – Chairman Drilling Managers Forum



Drilling Manager Forum

Responsibility

- Drilling and Well operations
- Well incidents
- Well Integrity
- Plug and Abandonment.

Network - Work groups

- Well Integrity Forum (WIF)
- Plug and Abandonment Forum (PAF)
- Well Incident Task Force (WITF)
- Ad hoc work groups



Well Control Focus (monthly meetings)

Agenda - Thursday September 22nd 2016 @ 10:00 - 14:30 hrs.

```
    1. 10:00-10:10 Safety brief and Approval of agenda
    2. 10:10-10:15 MoM-18.08.2016 – Approval and status
    3. 10:15-10:40 Case presentation/ company presentation
```

4.0 10:40-10:50 Well Control Incidents/ Well Incidents

5.0 10:50-11:00 Safety alerts/Lesson learned

6.0 11:00-11:30 Drilling/well control issues related to shallow reservoirs Barents Sea

11:30-12:30 Lunch

- 7.0 12:30-13:00 Guidance on calculating blowout rates and duration for use in environmental risk analysis
- 8.0 13:00-13:10 Task Force Capping and containment

| 9.0 | 13:10-13:15 | Revised mandate for DMF |
|------|-------------|---------------------------------|
| 10.0 | 13:15-13:20 | DMF Meeting schedule for 2017 |
| 11.0 | 13:20-13:40 | Guideline 082 – further process |
| 12.0 | 13:40-14:30 | AOB |



Well Control Focus

Final report from work group Capping, completed January 2017

NOROG-

NCS WELLS CAPPING STATUS REPORT 2016



Updated guidance for calculating blowout rates and duration, completed January 2017



Guidance on calculating blowout rates and duration for use in environmental risk analyses

Translated and updated version



Well Control Focus

Review of well control incidents 2016







Common guidelines

Register accord to internal company

<u>135 – Norwegian Oil and Gas Recommended guidelines for classification</u> and categorization of well control incidents and well integrity incidents



all actual and potential



| ocation: <location> (ig type: <rig type=""> Well type: <well type=""> ate: <date></date></well></rig></location> | Critical Issues: Free text evaluation |
|--|--|
| Direct Cause: | Underlying Cause: |
| Prognosis incorrect | Risk accepted |
| Shallow gas | Error in program / procedure |
| Shallow water flow | Procedure not followed |
| Incorrect mud weight | Lack of competence |
| Swabbing | Communication error (missing, wrong, incomplete, etc.) |
| Ballooning | Incorrect use of equipment |
| HC accumulation below barrier element | Equipment failure |
| Surface pressure control system failure | BOP failure |
| Downhole mechanical barrier failure | Other: |
| Downhole cement / casing barrier failure | |
| Other: | |




Common guidelines


117 Recommended guidelines for Well Integrity

| CHAPTER 311 | | |
|---|--|--|
| WELL BARRIER SCHEMATICS FOR THE OPERATIONAL PHASE11 | | |
| 1. Introduction | | |
| 2. Background | | |
| Guidelines of minimum data | | |
| 4. Discussion on minimum data | | |
| 4.1 The formation strength should be indicated for formation within the barrier envelopes | | |
| CHAPTER 4 | | |
| WELL INTEGRITY WELL CATEGORIZATION | | |
| 1. Objective | | |
| 2. Abbreviations & Definitions | | |
| Abbreviations | | |
| Definition of terms | | |
| 3. Background | | |
| 4. Philosophy | | |
| | | |



Sharing to be better





No 4 Question


- 1) What do you notice about the value of the SIDP
 - Kill mud weight: 1,75 sg (Pore Pressure 1,723 sg EMW + 2 point safety margin)
- Commenced well kill operation as per Drillers Method
 - Started circulating out influx with 30 SPM, ICP actual: 50 bar, only 35% returns, reduced rate to 25 SPM and then 20 SPM, attempting to reduce loss rate but losses ranged from 70 - 100% No. 5 Question

1) Why do think the losses were so great and circulation could not be established?

A joint efforts by Norwegian Oil and Gas and NSA (Norwegian Shipowners Association) establishing a task force with focus on reducing well incidents.

Communicate actual well control incidents that have recently occurred on the NCS so lessons are shared and understood.

A number of case histories are available and has been circulated to all installations.







Question 2: do you see any shortcomings with the top stand with pressure on Drill string and annulus?

Float leaking (non-ported flapper type)

Circulating sub opened

«Sharing to be better»





Sharing to be better #1, Well control incident in 9,5 inch section

Sharing to be better #2, Well control incident in 8,5 inch section

Sharing to be better #3, Shallow gas incident

Sharing to be better #4, Gas influx from shale

Sharing to be better #5, Well control incident - Completion

Sharing to be better #6, Well control incident - pulling tie-back string

Sharing to be better # 7, Drilling 8,5 inch reservoir section, HPHT

Sharing to be better #8, Incident - Drilling of reservoir section

Sharing to be better #9, Shallow gas incident

Sharing to be better #10, Incident - Work-over operations

Sharing to be better #11, Well control incident in 8,5 inch section

Sharing to be better #12, Swabbed kick from shallow reservoir

Sharing to be better #13, Total mud loss followed by kick from a semisubmersible drilling unit in "karstified carbonates"

Sharing to be better #14, Well control incident during plugging

Sharing to be better #15, Well controll incident during completion operations



Share to be better

If one fails, we will all suffer