

Equinor Energy AS Postboks 8500

Forus 4035 Stavanger

Vår saksbehandler Amir Gergerechi

Deres ref.

Vår ref. (bes oppgitt ved svar) Ptil 2019/122/AG Dato

Dear Sirs

Investigation of the incident in well 7132/2-1, unintentional disconnection of the lower marine riser package (LMRP) on *West Hercules*, 16 January 2019

The Petroleum Safety Authority Norway has completed its investigation of the above-mentioned incident. Our report is attached.

We have identified breaches of the regulations. See chapter 6 of the report. Chapter 6.1 describes the non-conformities.

The identified nonconformity concerns:

- see-to-it duty.

The report describes identified nonconformities. We would request an explanation of the way the nonconformity concerning the see-to-it duty will be dealt with.

We would request a response to this letter by 29 May 2019. We also request that this letter and report be made known to the elected officers for the workforce, including the safety delegates.

The report will be published on our website on 6 May 2019.

Yours faithfully

Rune Solheim, by authority head of supervision

Amir Gergerechi principal engineer

This letter has been approved electronically in the PSA and accordingly bears no signatures

Attachments: 4