



PETROLEUMSTILSYNET

Maersk Drilling Norge AS
Postboks 134 Forus
4065 Stavanger

Vår saksbehandler
Ola Heia

Deres ref.

Vår ref. (bes oppgitt ved svar)
Ptil 2018/1448/OHe/SL/SH/EiSo

Dato
6.3.2019

Dear Sirs

Report of the investigation into the incident where two tubular stands detached from the fingerboard on *Maersk Invincible*

While the mobile drilling facility *Maersk Invincible* was engaged on a completion operation in well 2/8-N-4, two tubular stands became detached from the fingerboard and fell out across the drill floor.

The direct cause of the incident was that the locking mechanism in the latches in the fingerboard failed to work as intended.

We have investigated this incident and attach our report, which has identified breaches of the regulations. The report describes identified nonconformities, and we would request an explanation of how these will be dealt with.

We would request a response to this letter no later than 8 April 2019. We also request that this letter and the report are made known to the elected officers for the workforce, including the safety delegates.

Should you discover factual errors in the report, we would request that you contact us within a week of the date of this letter.

The report will be published on www.ptil.no a week after the date of this letter at the earliest.

Yours faithfully

Irja Viste-Ollestad, by authority
head of supervision

Ola Heia
principal engineer

Attachments: 3