

Odfjell Drilling AS
Kokstadflaten 35
5257 Kokstad

Our case officer

[REDACTED]

Your ref.

Our ref. (please quote when replying)
Havtil 2025/1512/AG

Date
22 April 2026

Report following the investigation of a well control incident in well Q-21 on the Troll field involving Deepsea Bollsta

From 25 September 2025 to 19 March 2026, we investigated the well control incident in well Q-21 on the Troll field involving Deepsea Bollsta.

Our report is attached.

If you notice any factual errors in the report, please contact us within one week of the date of this letter. The report will be published on www.havtil.no.

The report includes a description of identified non-conformities, and we request that you provide an account of how these non-conformities will be addressed. The report also identifies an improvement point where there appears to be a breach of the regulations, and we request your assessment of this. Please respond by 26 May 2026.

The identified non-conformities concern:


- Noise level in the driller's cabin during well control incident
- Separation of HVAC 1 and HVAC 2 rooms
- Failure to use differential pressure data
- Lack of maintenance of differential pressure gauges
- Inadequate updating of technical documentation
- Inadequate formulation of requirements in the well control manual


The following improvement point was identified:

- Handling of hazard and accident situations

We also request that this letter and the report be made known to employee representatives, including the safety delegates.

Sincerely


Acting Head of Supervision


Investigation leader

This letter has been electronically certified by the Norwegian Ocean Industry Authority and therefore has no signature.

Attachments: 2